

Renovation of Shihmen Reservoir for Sustainability

Paul S.T. Hsu Ph. D., PE

2017.06




This learning material was not prepared by ADB. The views expressed in this document are the views of the author/s and do not necessarily reflect the views or policies of the Asian Development Bank or its Board of Governors, or the governments they represent. ADB does not guarantee the accuracy of the data included in this presentation and accepts no responsibility for any consequence of their use. The countries listed in this presentation do not imply any view on ADB's part as to sovereignty or independent status or necessarily conform to ADB's terminology.

Presentation Outline

- 1. Environment Induced Water Challenges in Taiwan
- 2. Role of Reservoir and Condition of Siltation
- 3. Problems Caused by Typhoon Aere in 2004
- 4. Measures to Secure Potable Water Supply Following Storms
- 5. Measures to Secure Reservoir Volume for Sustainability
- 6. Concluding Remarks

1. Environment Induced Water Challenges in Taiwan







Environment and Water Challenges

High Young/Fragile Mountain Geology & Frequent w/steep River Earthquake Slope Water Challenges Frequent Uneven Typhoon Rainfall w/Intense Distribution Rainfall

Challenge 2 – Steep Slope

Comparison of River Slope





- High intensity, Long duration.


Taiwan Typhoon Rainfall Records

| Rainfall | | Typhoon | Location | | |
|----------|------|---------|---------------------------|-----------------|--|
| Ranking | mm | Yr. | Typhoon | Location | |
| 1 | 3060 | 2009 | MORAKOT | Chiayi County | |
| 2 | 2139 | 2001 | NARI | New Taipei City | |
| 3 | 2162 | 1969 | Tropical Storm FLOSSIE | Taipei City | |
| 4 | 1987 | 1996 | HERB | Chiayi County | |
| 5 | 1834 | 1987 | LYNN | Taipei City | |
| 6 | 1774 | 2012 | SAOLA | Yilan County | |
| 7 | 1672 | 1967 | CARLA | Yilan County | |
| 8 | 1611 | 2008 | SINLAKU | Taichung City | |
| 9 | 1561 | 2005 | HAITANG | Pingtung County | |
| 10 | 1546 | 2004 | AERE | Miaoli County | |

Challenge 4-**Uneven Rainfall Distribution**

Average Annual **Precipitation in Taiwan** (1949~2006): 2,515 mm

| Region | Percent of Rainfall in Dry Season | | |
|---------|-----------------------------------|--|--|
| North | 37% | | |
| Central | 31% | | |
| South | 18% | | |
| East | 28% | | |




2. Role of Reservoir and Condition of Siltation

Water Use in Taiwan

Annual Rainfall Volume: 90×10⁹m³

Total Reservoir Volume: 1.90×10⁹m³



Volume of Main Reservoirs in Taiwan

Unit: 106m3

| No. | Reservo | oir Name | Initial Volume | Current Volume |
|-----|--------------|----------|----------------|----------------|
| 1 | Shinshan | (新 山) | 10.00 | 9.97 |
| 2 | Feitzai | (翡翠) | 406.00 | 380.04 |
| 3 | Shihmen | (石 門) | 309.12 | 204.71 |
| 4 | Baoshan | (寶 山) | 5.47 | 5.50 |
| 5 | Yuheshan | (永和山) | 29.58 | 30.23 |
| 6 | Minder | (明 德) | 17.70 | 12.36 |
| 7 | Dergi | (德 基) | 262.21 | 191.40 |
| 8 | Wusher | (霧 社) | 150.00 | 44.86 |
| 9 | Sunmoon Lake | (日月潭) | 171.62 | 142.56 |
| 10 | Liyitan | (鯉魚潭) | 126.07 | 118.46 |
| 11 | Zenyutan | (仁義潭) | 29.11 | 26.34 |
| 12 | Lantan | (蘭 潭) | 9.80 | 9.80 |
| 13 | Tsengwen | (曾 文) | 712.71 | 462.68 |
| 14 | Nanhua | (南 化) | 154.41 | 95.00 |
| 15 | Wushantou | (烏山頭) | 168.83 | 78.28 |
| 16 | Mutan | (牡 丹) | 31.18 | 26.41 |
| 17 | Chengkung | (成 功) | 1.08 | 1.21 |
| SUM | | - | 2,594.89 | 1,839.81 |


Location of Shihmen Reservoir



A View of Shihmen Reservoir

■ Drainage Area: 763 km²

■ Completed: 1963



Plan View of Original Outlet Structures of Shihmen Reservoir



Scale 1:10,000

Current Water Budget of Shihmen Reservoir

■ Current Reservoir Volume: 200×106m³

| Average Annual Inflow (10 ⁶ m ³) | Average Annual Outflow (10 ⁶ m ³) | | |
|---|--|---------------|-----------------|
| | Irrigation | Potable Water | Flood Discharge |
| 1 500 | 456 | 400 | 710 |
| 1,560 | 850 | | 710 |

Shihmen Reservoir Discharge Structures

- Designed Based on Traditional Approach
 - > Small bottom outlet
 - ➤ Large spillway

| Structure | Intake Elevation (m) | Design Capacity (cms) |
|---------------------------|----------------------|-----------------------|
| Diversion Tunnel | EL. 135.0 | 4,700 (plugged) |
| Permanent River Outlet | EL. 169.5 | 34.0 |
| Power Intake | EL. 169.5 | 2@68.6=137.2 |
| Irrigation Canal | EL. 193.5 | 18.4 |
| Tunnel Spillway | EL. 220.0 | 2@1,200=2,400 |
| Spillway | EL. 235.0 | 11,400 |



Store TurbidWaterDischarge





Severe Reservoir Siltation

3. Problems Caused by Typhoon Aere in 2004

Facts About Typhoon Aere

- Date of Occurrence: August 24 and 25, 2004
- Average Basin Rainfall: 973 mm
- Total Inflow Volume: 742 X 106m³
- Peak Inflow Discharge: 8,600 cms
- Peak Outflow Discharge: 6,270 cms

View of Turbid Reservoir After the Storm



View of Log Accumulation in Upstream Reach



2017/06

View of Floating Debris in the Reservoir




View of Log Accumulation Near the Dam





Spillway Discharge During Aere





Mudflow in Penstock



No Tap Water After Typhoon Aere








Problems with Turbine & Valve



Guide Vane




PRO Damage




Wicket Gate




PRO Repair




PRO Trashrack Damages Caused by Log/Mud Blockage




Density Current in a Reservoir



Turbidity Variation at Shihmen Canal Intake Following Typhoon Aere



Turbidity at Different Location in Shihmen Reservoir Following Typhoon Aere



Problems Caused by Typhoon Aere

- Turbidity of water at intake too high to be purified
- Reservoir siltation of 27.88 X 10⁶m³, caused permanent reduction in water supply capability
- Submerged debris clogged intake structures affecting normal operations of intake and hydro units
- Discharge capacity can not handle PMF, causing safety concern

Siltation Caused by Major Typhoon Events

| Yr. 年度 | Typhoon 颱風名稱 | | Deposition 淤積量(m³) |
|-----------------|-----------------|-----|-----------------------|
| 1963.05~1964.03 | Gloria | 葛樂禮 | 1,947 |
| 1969.05~1970.06 | Elsie | 艾爾西 | 503 |
| 1971.06~1972.12 | Bess | 貝 絲 | 523 |
| 1984.11~1985.11 | Nelson | 尼爾森 | 369.5 |
| 1995.11~1996.11 | Herb | 賀 伯 | 867 |
| 2004.03~2004.12 | Aere | 艾 利 | 2,788.4 |
| 2006.12~2007.12 | Krosa | 柯羅莎 | 962.4 |
| Sur | 7,960.3 | | |
| Total Sil | 9,386.4 | | |
| Sum/Total si | 84.8% | | |

4. Measures to Secure Potable Water Supply Following Typhoon

Temporary Measure

- Constructed a floating pumping facility in the reservoir
- Constructed a large storage tank on the right abutment of the dam to receive flow from the pumping facility
- Constructed an above ground pipe with a head tank to link flow from the storage tank to existing water main
- The design discharge was 980,000 CMD

Floating Pumping Facility (1/2)




Floating Pumping Facility (2/2)

Overview of the Pumping Facility



Head Tank



Above Ground Pipe w/Decoration








New Permanent Intake Project Design Guidelines

- Discharge Capacity: 140,000 CMD
- Intake Level: EL. 220、EL. 228、EL. 236
- Discharge Connections
 - ➤ Water Company's Pipeline
 - Existing Irrigation Canal
 - **≻** Afterbay


Overall Layout of New Intake Project




Original Landscape of The New Intake



Plan View of the New Intake




Section View of Intake Tunnels






| | 點號 | N | E | 水平角 | 垂直角 |
|---|-----|-----------|----------|-------|-----|
| | BU | 2744700.4 | 274293.8 | | |
| | EU | 2744775.3 | 274288.6 | | |
| | BM | 2744754.0 | 274328.1 | | |
| | BL | 2744692.2 | 274298.6 | | |
| ı | TPO | 2744740 9 | 27/270 0 | 58 9° | |


说明:1.本圖單位除註明外,其餘為m 2.計畫高為管線中心高





Scale 1:200 10 20m Scale 1:500

Section View of Intake Shaft




Photos of New Intake

Top Level Intake




Control Room



5. Measures to Secure Reservoir Volume for Sustainability

- Existing Outlet Modification to Enhance Silt Sluicing
- New Silt-Sluicing Tunnel at Dawanping
- Dredged Sediment Sorting and Flushing Facilities at Amuping


Reservoir Siltation Profile and Separation of Material at about Section 20




Shihmen Reservoir Existing Outlet Modifications to Enhance Silt Sluicing

| Outlet | Design Q (cms) | Type of Modification | |
|------------------------------|-------------------|--|--|
| Shihmen Irrigation Canal | 18 | | |
| Permanent River Outlet (PRO) | 33 | Howell-Bunger Valve changed to Jet Flow Gate | |
| Penstocks | 2@68 | Unit 1: Bifurcation to both units | |
| CHSCOCKS | 2600 | Unit 2: Convert to silt Sluice way Q=300 cms | |


Plan & Elevation Views of Penstocks




Penstock Modification as A Silt Sluice Way



Silt Sluice Way Profile



3D View of Penstock Converted Silt Sluice Way



Construction Photos of Penstock Silt-Sluice Way














Operation of Spillway & Penstock Silt Sluice Way




2013 Typhoon Soulik in Shihmen Reservoir




Location of Amuping & Dawanping Silt Sluice Tunnels




Plan View of Dawanping Tunnel (Q=1,600cms)




Profile of Dawanping Silt-Sluice Tunnel




Dawanping Tunnel Intake



Dawanping Tunnel Outlet




Plan View of Amuping Tunnel




Amuping Facility Design Concept

- Dredge material upstream from section 20
- Sediments deposited in this region is coarser
- Designed to remove 640,000 m³ of deposits of per year
- Estimated that roughly half of the deposits can be used as concrete aggregates. Sorting facility will be used to segregate them from fines
- Fine materials shall be temporarily stored in a 200,000 m³ detention basin. The material shall be flushed to the river by excess reservoir water prior to and during typhoon


Intake & Cross-Section of Amuping Tunnel




Profile of Amuping Tunnel




隧道段≒3,565m



Outlet of Amuping Tunnel



Schematic of Amuping Sediment Removal System



Maintaining Reservoir Volume

Unit: 103m3

| Average | Average Annual Sediment Outflow | | | | | | | |
|------------------------------|---------------------------------|---|------------------------------------|--|-------------------|-----------------------------------|-------|--|
| Annual Sediment Inflow | PRO Sluice way | Power Plant Sluice way after Power Plant modification | Dawanping Silt Sluice Tunnel | Dredged Silt Through Amuping Tunnel | Dedging at Dam | Dredging u/s from Reservoir | Sum | |
| 2 420 | 150 (4%) | 1,020 (30%) | 710 (21%) | 640 (19%) | 500 (15%) | 400 (12%) | 3,420 | |
| 3,420 | 55% | | | 19% | 26% | | 100% | |

Sufficient Outflow Capacity for PMF

| | PMF (cms) | Outflow Capacity (cms) | | | | | |
|---|--------------|------------------------|-----------------------------|--------------------|---------------------------|-------------------|--------|
| Yr. | | Spillway | Penstock Silt Sluice way | Tunnel Spillway | Dawanping Silt Sluice way | Amuping Tunnel | Total |
| 1959 (original Planning) | 10,900 | 11,400 | Ι | _ | _ | Ι | 11,400 |
| 1963 (After Typhoon Gloria) | 11,750 | 11,400 | _ | 2@1,200 | _ | _ | 13,800 |
| 2014 (3 rd Dam Safety Analysis) | 14,500 | 11,400 | 300 | 2@1,200 | 1,600* | 600* | 16,300 |


^{*}Construction under planning

6. Concluding Remarks

Concept of Sustainability

The World Commission on Environment and Development , **WCED** - Our Common Future, 1987

"Sustainable development is development that meets the needs of the present without compromising the ability of future generations to meet their needs."



What We Have Learned and Our Willingness to Share

- Reservoir sedimentation is a key issue on water resources management in Taiwan
- Traditional design of small bottom outlet with large overflow spillway will cause large sediment accumulation and make a reservoir unsustainable. The design approach should be modified
- In addition to Shihmen Reservoir, Taiwan is also doing renovation of other reservoirs in southern region
- Renovation experiences learned from these reservoirs can also be implemented to existing reservoirs in other countries
- ADB is invited to visit Taiwan to gain a deeper understanding of the renovation works