



This is not an ADB material. The views expressed in this document are the views of the author/s and/or their organizations and do not necessarily reflect the views or policies of the Asian Development Bank, or its Board of Governors, or the governments they represent. ADB does not guarantee the accuracy and/or completeness of the material's contents, and accepts no responsibility for any direct or indirect consequence of their use or reliance, whether wholly or partially. Please feel free to contact the authors directly should you have queries.

O&M Cases Sharing and Advice

Xuegeng Luo

August 08, 2022



为人居环境更美好
Making our living environment better

www.bewg.net

1.1 O&M Cases Sharing-Case in South East area



Chemical dosing unit

Water treatment plant with 228 MLD

Before: poor condition and low efficiency, almost half of the equipment under breakdown, production less than 50%. After operated by professional O&M contractor, production achieved design load.




1.1 O&M Cases Sharing-Case in South East area

Water treatment plant with 228MLD



Alum storage tank



1.1 O&M Cases Sharing-Case in South East area

Water treatment plant with 228MLD

Clarifier



1.1 O&M Cases Sharing-Case in South East area

Water treatment plant with 228MLD

One of the production pump station



1.2 O&M Cases Sharing-Case in China

Single plant: Beijing Daoxiang Lake Underground STP under BEWG, 80 MLD



1.3 O&M Cases Sharing-Case in China

Cluster: Water asset (including pipe net) O&M in Guangxi Guigang City



1.4 Summary-O&M Professional Services




What the Contractor provide



What the Employer get

2 Advice/Suggestions





BEWG
北控水务

Thank you

For your attention!

